Report Form - Requalification by External Visual Inspection
Reference: Clause 24.7.1(b) of CSA B339-25

COMPANY: _____ DATE: _____ _____
Month Year

FACILITY LOCATION: _____ RESPONSIBLE MANAGER: _____
(Signature)

FACILITY REGISTERED MARK: _____

CYLINDER IDENTIFICATION						PROTECTIVE COATING		CYLINDERS INSPECTED FOR								DISPOSITION		
Serial Number	Owner Name or Symbol	Specification and Service Pressure	Manufacturer	Date of Mfg. (mm/yy)	Dimensions (Diameter x Length)	Type	Condition	Corrosion and Pitting	Dents	Cuts, Digs and Gouges	Leaks	Fire Damage	Bulges	Neck Defects	Attachments	Disposition	Date Inspected (dd/mm/yy)	Inspector Initials
110506	*123 Inc.*	*DOT-4BA240*	*M####*	*01/90*	*12.2" x 18"*	*Paint*	*Good*	*√*	*√*	*√*	*√*	*√*	*√*	*√*	*√*	*OK*	*01-06-2012*	*TC*
296087	*TDG Cyl.*	*TC-4BWM16*	*M####*	*03/02*	*15.1" x 46.6"*	*Galvanized*	*Fair*	*SC***	*√*	*√*	*√*	*√*	*√*	*√*	*√*	*SC*	*01-06-2012*	*TC*

Disposition code: **OK - Return to Service**
SC - Scrap (Condemned)

REMARKS:

*****Cylinder serial number 296087 - Condemned due to excessive corrosion***