

**WINNIPEG PROXIMITY ISSUES  
RIVERS SUB (PORTAGE JCT-M.P 6.19)**

#1



Rear of 'Re-Fit' Center where a fatality occurred in 2009. The parking lot backs onto CN right of way. Small 3 foot wooden fence.

#2




A School soccer field just west of the above location on the south side of the tracks. No fence erect and a clear beaten path leads to the tracks.

**WINNIPEG PROXIMITY ISSUES  
RIVERS SUB (PORTAGE JCT-M.P 6.19)**

On picture #3, the soccer field bleachers are almost on the CN right of way. Another fatality occurred at this location in the summer of 2011.

#3



#4

